

MATERIAL SAFETY DATA SHEET

Manufacture's Name **Address** **Telephone Number**
Westlake Chemical 900 Highway 108 (337) 583-2200
Corporation Sulphur, LA 70665

Product Name: **BUTADIENE**
Date of Issue: January 22, 2002
Revised Date: April 19, 2011

SECTION I PRODUCT IDENTIFICATION

Chemical Names/Synonyms: **Butadiene Product; Butadienes, Inhibited**
Chemical Formula: **C₄H₆**

SECTION II HAZARDOUS INGREDIENTS AND EXPOSURE LIMITS

Component	CAS No.	Wt%	Exposure Limits
1,3 Butadiene	106-99-0	68 - 86	TLV (ACGIH): 10PPM OSHA pel 8 HR. twa: 1 PPM
Isobutylene	115-11-7	5 - 10	
N-Butene	106-97-8	5 - 10	TLV (ACGIH): 800ppm
1-Butene	106-98-7	5 - 10	
t-2-Butene	624-64-6	1 - 2	
c-2-Butene	590-18-1	1 - 2	
Vinyl Acetylene	689-97-4	1 - 3	

SECTION III. CHEMICAL AND PHYSICAL PROPERTIES

Boiling Point (at 760 mm Hg): 24°F (-4°F)
Melting Point: -164.1°F
Evaporation Rate (Butyl Acetate=1): Not applicable – Gas
Vapor Density: 1.9
Molecular Weight: 54.1 grams/mole
Appearance And Odor: A non-corrosive, colorless, flammable gas; mild
aromatic odor.
Specific Gravity (Water=1): .62 ^(20°/4°)

The information above is for pure 1,3 – Butadiene.

SECTION IV FIRE AND EXPLOSION HAZARD DATA

Flash Point: 105°F (Liquid)
(Method)

Auto Ignition Temperature: 788°F

Flammable Limits In Air: LFL: 2.0%; UFL: 12%

National Fire Protection Association Hazard Identification Code

Health: 2 **Flammability:** 4 **Reactivity:** 2 Other:

Fire Extinguishing Media:* Butadiene is a flammable gas. Try to stop the flow of the gas and use a water spray to cool fire-exposed containers.

Special Fire Fighting Procedures: Wear a self-contained breathing apparatus (SCBA) with a full face piece operated in the pressure-demand or positive-pressure mode.

Unusual Fire Or Explosion Hazards: When mixed with air, butadiene forms potentially explosive peroxides. Direct fire-fighting procedures toward stopping the flow of gas and removing uninvolved containers of butadiene from the fire area. Warning: Heat and/or and insufficient concentration of inhibitor can cause butadiene to polymerize violently with the rupture of the container. Butadiene vapor is heavier than air and can travel a considerable distance to a low-lying source of ignition and flash back.

SECTION V. HEALTH HAZARDS

Acute Health Effects: May cause irritation to the eyes, nose, and throat. Symptoms include rapid respiration, diminished mental alertness, fatigue, muscular incoordination and loss of consciousness. Can act as an asphyxiant by displacing breathable air.

Chronic Health Effects: Material is a suspected carcinogen. Exposure may cause leukemia, non-Hodgkins lymphoma and anemia.

Medical Conditions Aggravated By Exposure: None reported.

Primary Routes of Entry:

Inhalation: Inhalation of high concentrations can cause unconsciousness and death. Human systemic effects by inhalation: Cough, hallucinations, distorted perceptions, changes in the visual field and other unspecified eye effects.

Eyes / Skin: The vapors are irritating to eyes and mucous membranes. If spilled on skin or clothing, it can cause burns or frost bite (due to rapid vaporization).

Ingestion: Unlikely route of exposure.

Carcinogenicity Status: According to Sax, material is an experimental carcinogen and teratogen, Butadiene is regulated by OSHA Standard 1910.1051.

SECTION VI FIRST AID PROCEDURES

Inhalation: Remove the exposed person to fresh air. If breathing has stopped, give artificial respiration. If breathing is difficult, give oxygen. Caution: Would be rescuers must be concerned about their own safety if atmospheric oxygen has been displaced by butadiene gas; wear an SCBA, if necessary.

Eyes: Immediately flush eyes, including under the eyelids, gently but thoroughly with plenty of running water for at least 15 minutes.

Skin: Wash the affected area with soap and water. Treat for frostbite damage (cryogenic injury) if contact with liquid butadiene has occurred.

Ingestion: Unlikely route of exposure.

Secure prompt medical assistance for further treatment, observation and support after first aid.

SECTION VII PERSONAL PROTECTION

Respirator: Wear a NIOSH-approved respirator in accordance with table 1 in the 1,3 Butadiene standard 1910.1051. Follow OSHA respirator regulations (29 CFR 1910.134). Consult OSHA standard 1910.1051 for engineering control requirements.

Skin: Wear impervious gloves, boots, aprons, gauntlets, etc., as required by the specific work environment to prevent skin contact.

Eyes: Wear protective eyeglasses or chemical safety goggles per OSHA eye and face protection regulations (29 CFR 1910.133). Where splashing is possible, wear a full face shield.

Ventilation: Install and operate both general and local exhaust systems with maximum explosions-proof ventilation powerful enough to maintain airborne levels of butadiene below the OSHA PeI standard.

Contaminated Equipment: Launder contaminated clothing before wearing. Remove this material from shoes and equipment.

Other: Make eyewash stations, safety/quick-drench showers, and washing facilities available in work areas. Contact lenses pose a special hazard; soft lenses may absorb irritants and all lenses concentrate them.

Work Hygienic Practices: Practice good personal hygiene; always wash thoroughly after using this material. Keep it off your clothing and equipment. Avoid transferring it from your hands to your mouth while eating, drinking or smoking. Do not eat, drink or smoke in any work area.

SECTION VIII REACTIVITY DATA

Hazardous Thermal Decomposition Products: Burning produces carbon dioxide and/or carbon monoxide.

Stability: Inhibited Butadiene is stable in closed, pressurized, airtight containers at room temperature under normal storage and handling conditions and when the concentration of inhibitor remains at effective levels; otherwise, hazardous polymerization can occur.

Incompatible Materials: Dangerous reactions may occur between butadiene and air, phenol, chlorine dioxide, and crotonaldehyde. When heated to just above its melting point under pressure, butadiene may undergo a violent thermal decomposition. Avoid combining it with ozone, nitrogen dioxide, copper and its alloys, and strong oxidizing agents such as chlorine, permanganate, or dichromate salts.

Incompatible Conditions: Prevent contact with air, heat, sparks, open flame or any possible free radical polymerization initiators such as hydroquinone.

Hazardous Polymerization: If not stable, hazardous polymerization can occur.

Comments: Butadiene is self-reactive; the added inhibitor minimized self-polymerization reactions. Determine the overall quality of the butadiene, including the extent of peroxide formation and/or by-products of self-reaction, before use. Do not use if highly contaminated.

SECTION IX SPILL, LEAK AND DISPOSAL PROCEDURES

Spill and Leak: Notify safety personnel, eliminate sources of ignition, provide adequate ventilation, limit access to necessary personnel only and remove leaking containers to a safe place, if feasible. Those involved in cleanup need protection against inhalation of butadiene gas. Try to stop the flow of gas.

Waste Management: Due to processing, reformulation, etc., it is the responsibility of the user to determine the status of waste material. Dispose of according to federal, state and local regulations.

SECTION X. ADDITIONAL PRECAUTIONS

Storage: Store butadiene in pressurized containers in a cool, dry area away from incompatible chemicals. Outside, isolated, or detached storage is recommended. Avoid moisture or air contamination of storage facilities by installing engineering systems and monitoring equipment.

Other: Special Handling/Storage: Preplan for routine use and emergency response. Protect containers from physical damage. Electrically ground and bond all containers used in shipping and transferring operations to prevent static sparks. Carefully follow your supplier's recommendations concerning shelf life, rotation of inventory, and monitoring the inhibitor levels in the butadiene product.

SECTION XI. TRANSPORTATION DATA

Department of Transportation: (49 CFR 172.101-2)
Proper Shipping Name: Butadienes, Inhibited
Placards Hazard Class: 2.1 (flammable)
Labels: Flammable Gas
UN/NA ID. No.: UN1010
Reportable Quantities: 10 lbs.

SECTION XII OTHER REGULATORY DATA

This Material Is Regulated Under:

Occupational Safety and Health Administration: Air Contaminant (29 CFR 1910.1000 Subpart Z)

OSHA 29 CFR 1910.119 Process Safety Management: Listed. This material is flammable per 1910.1200.

TSCA: Material is listed in TSCA inventory.

40 CFR Part 68 (RMP): Listed

Superfund Amendments Reauthorization Act: The threshold planning quantity for material is 10,000 lbs.

SECTION XIII USERS RESPONSIBILITY

This bulletin cannot cover all possible situations which the user may experience during processing. Each aspect of the user's precautions may be necessary. All health and safety information contained in this bulletin should be provided to employees and/or customers. Westlake Petrochemicals Corporation must rely on the user to use this information to develop appropriate work practice guideline and employee instructional programs specific to the user's operation.

SECTION XIV DISCLAIMER OF RESPONSIBILITY

As the conditions and methods of use are beyond our control, we do not assume any responsibility and expressly disclaim any liability for any use of this material. Information contained herein is believed to be true and accurate but all statements or suggestions are made without warranty, expressed or implied, regarding accuracy of the information, the hazards connected with the use thereof. Compliance with all applicable federal, state and local laws and regulations regarding the use, storage, sale, transport or disposal of this material is the responsibility of the user.